DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/20/2007 FORM APPROVED OMB NO. 0938-0391

PRÉFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) PRÉFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLET TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	' '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - BLDG V-2 (0206)		(X3) DATE SURVEY COMPLETED 10/04/2007	
NAME OF PROVIDER OR SUPPLIER CHERRY HOSPITAL STREET ADDRESS, CITY, STATE, ZIP CODE 201 STEVENS MILL ROAD GOLDSBORO, NC 27530 (X4) ID PREFIX TAG SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) K 033 NFPA 101 LIFE SAFETY CODE STANDARD Exit components (such as stairways) are enclosed with construction having a fire resistance rating of at least one hour, are arranged to provide a continuous path of escape, and provide protection against fire or smoke from			344003	B. WING				
PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)					STREET ADDRESS, CITY, STATE, ZIP CODE 201 STEVENS MILL ROAD			
Exit components (such as stairways) are enclosed with construction having a fire resistance rating of at least one hour, are arranged to provide a continuous path of escape, and provide protection against fire or smoke from	PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREF	X (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP		ULD BE	(X5) COMPLETION DATE
This STANDARD is not met as evidenced by: By observation on 10/3/07 at approximately noon the exit stainwell on the first floor (East side) had metal trash cans storing mop heads. (the mop storage was removed at the time of the survey)	K 033	Exit components (sur enclosed with construction resistance rating of a arranged to provide a and provide protection other parts of the build the exit stairwell on the metal trash cans store	ch as stairways) are uction having a fire ut least one hour, are a continuous path of escape, on against fire or smoke from Iding. 8.2.5.2, 19.3.1.1 not met as evidenced by: 0/3/07 at approximately noon the first floor (East side) had ring mop heads. (the mop	K	033			12/5/07

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE